


FIG. 1

2/4



SLAVE PHASE COUNTER


C_{s1}

C_{sb}

C_{sc}

C_{sa}

FIG. 2(b)






FIG. 3




FIG. 4




FIG. 5




FIG. 6
(PRIOR ART)